



241. Lead sheets misaligned @ SW



240. Dome Inspection Descent 2 @ SW



238a. Dome NW Rigged Access




253. Peristyle cornice leadwork & LC downtape @ SW



247. Old soldered fixing failed @SE



242. Lead sheets lifted & misaligned



248. Leadwork lifted @ S face



243. Golden Gallery Base LC coronal conductor tape & fittings attached @SE



249. Leadwork tearing @S




244. lead flashing under asphalt walkway



250. Vertical crack up lead sheet S face



245. Descent 3 loose copper cleat SE downtape Descent 3




246. Descent 3 loose copper cleat & downtape @SE



252a. Lead staining & missing section



252b. Lead staining & missing section @ SW



Clip Detail



251. lead sheet tear on SE face



252. Lead sheet tear

DO NOT SCALE - ASK FOR DIMENSIONS.  
USE ONLY FOR THE PURPOSE INDICATED BELOW.  
THE INTELLECTUAL PROPERTY CONTAINED IN THIS DRAWING REMAINS THE PROPERTY OF STONE TECHNICAL SERVICES WHOSE RIGHTS ARE TO BE IDENTIFIED WITH THE COPYRIGHT, DESIGN AND PATENTS ACT 1988

NOTES



KELLAW ROAD,  
DARLINGTON, DL1 4YA

TEL: 01325 282794  
FAX: 01325 487329  
MOBILE: 07971 173626

EVANS HOUSE, 107  
MARSH ROAD, PINNER,  
MIDDLESEX, HA5 5PA

TEL: 0208 4296700  
FAX: 02084296755



PART OF THE STONE TECHNICAL GROUP OF COMPANIES

PROJECT:	ST PAUL'S CATHEDRAL
DRAWING TITLE:	ROOF PHOTOGRAPH AND LOCATIONS
SCALE:	NOT TO SCALE @ A1
DRAWN BY:	J LEWIS
DATE:	JANUARY 2013
DRAWING NO:	001
REVISION:	-